



# EPA Monitoring Data Summary



*Disclaimer* - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the written requirements issued by the NSW Environment Protection Authority. To the best of Kimbriki Environmental Enterprises' knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior written consent from Kimbriki Environmental Enterprises. For more details on publication of pollution monitoring data please refer to the NSW EPA Website, [www.epa.nsw.gov.au](http://www.epa.nsw.gov.au)

Monitoring Period	Jan-23						
Date Published	13 February 2023						
EPA Licence No.	13091						
EPA Licence Hyperlink	<a href="https://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=211659&amp;SYSUID=1&amp;LICID=13091">https://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=211659&amp;SYSUID=1&amp;LICID=13091</a>						
Licensee Name	KIMBRIKI ENVIRONMENTAL ENTERPRISES PTY LIMITED						
Licensee Address	PO BOX 196, Terrey Hills, NSW 2084						
Monitoring Location (EPA Point 1)	<i>Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 1)</i>						
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Max. value	100 percentile limit	Non-compliances (yes/no)
Explanatory Notes	No surface water discharge occurred from this monitoring point during the month.						
Monitoring Location (EPA Point 2)	<i>Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 2)</i>						
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Max. value	100 percentile limit	Non-compliances (yes/no)
Explanatory Notes	No surface water discharge occurred from this monitoring point during the month.						



# EPA Monitoring Data Summary



Monitoring Location (EPA Point 3)		Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 3)					
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Max. value	100 percentile limit	Non-compliances (yes/no)
Explanatory Notes		No surface water discharge occurred from this monitoring point during the month.					
Monitoring Location (EPA Point 21)		Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 21)					
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Max. value	100 percentile limit	Non-compliances (yes/no)
Biochemical oxygen demand	mg/L (Note 1)	Special Frequency 1 (Note 2)	5	<2	<2	20	no
Nitrogen (ammonia)	mg/L (Note 1)	Daily during any discharge	7	<0.01	0.04	1	no
pH	pH	Daily during any discharge	7	7.18	7.93	6.5-8.5	no
Total suspended solids	mg/L (Note 1)	Daily during any discharge	7	5.0	150.0	50	yes
Explanatory Notes		No surface water discharge occurred from this monitoring point during the month.					
Monitoring Location (EPA Point 22)		Enclosed Ground Level Flare in the North-Eastern corner of the Premises. Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 22)					
Parameter	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Max. value	Lower Limit (Note 2)	Non-compliances (yes/no)
Residence Time	seconds	Continuous	Continuous	0.8	0.9	0.6	no
Temperature	°C (Note 1)	Continuous	Continuous	792.1	807.0	760	no
Explanatory Notes		(Note 1) °C (degrees Celsius) (Note 2) The parameter value must <b>be greater than</b> the Lower Limit specified					



# Non-compliances



*Disclaimer* - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the written requirements issued by the NSW Environment Protection Authority. To the best of Kimbriki Environmental Enterprises' knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior written consent from Kimbriki Environmental Enterprises. For more details on publication of pollution monitoring data please refer to the NSW EPA Website, [www.epa.nsw.gov.au](http://www.epa.nsw.gov.au)

Monitoring Period	Jan-23					
Date Published	13 February 2023					
EPA Licence No.	13091					
EPA Licence Hyperlink	<a href="https://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=211659&amp;SYSUID=1&amp;LICID=13091">https://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=211659&amp;SYSUID=1&amp;LICID=13091</a>					
Licensee Name	KIMBRIKI ENVIRONMENTAL ENTERPRISES PTY LIMITED					
Licensee Address	PO BOX 196, Terrey Hills, NSW 2084					
Monitoring Location (EPA Point 21)	Please refer to the map, <i>Kimbriki Monitoring Sites.pdf</i> , for location (EPA 21)					
Pollutant	Units of measure	Monitoring frequency required by licence	100 percentile limit	Date of non-compliance	Value	Five-day cumulative rainfall recorded on site (mm) (Note 1)
Total Suspended Solids	mg/L (Note 2)	Daily during any discharge	50	7/01/2023	56	49.0 (Note 3)
Total Suspended Solids	mg/L (Note 2)	Daily during any discharge	50	25/01/2023	150	38.55 (Note 3)
Explanatory Notes	<p>(Note 1) mm (millimetres)          (Note 2) mg/L (milligrams per litre)          (Note 3) While the 5-day cumulative rainfall at the time of exceedances on 7th and 25th January 2023 did not meet the five-day duration 90th percentile rainfall event allowance for discharge (being 62.1mm), the results are attributable to the western basins (EPA 21 and EPA 1) being used to treat runoff from intermittent rainfall that occurred in the days leading up to the exceedance events. During the process of preparing the western basins in readiness for further rainfall on 7th and 25th January 2023, rainfall occurred which caused the basins to overflow. Kimbriki performs daily inspections of sediment controls and proactively maintain controls by all means practical to ensure potential for suspended solids discharge is minimised. Kimbriki will also reduce the potential for discharging elevated suspended solids by constructing an up-gradient clean water diversion system which will significantly reduce the stormwater catchment of the western basins and reduce the volume of sediment-laden water to be treated on site (construction is planned for completion before end of 2023).</p>					



# Monthly Summary of EPA Monitoring Data - No Limit **KIMBRIKI**

*Disclaimer* - Monitoring data contained in this document is made available as required by Section 66(6) of the Protection of the Environment Operations Act 1997 and in accordance with the written requirements issued by the NSW Environment Protection Authority. To the best of Kimbriki Environmental Enterprises' knowledge, the data in this table is correct, except where specifically noted. The information and data in this table must not be published elsewhere by any means without prior written consent from Kimbriki Environmental Enterprises. For more details on publication of pollution monitoring data please refer to the NSW EPA Website, [www.epa.nsw.gov.au](http://www.epa.nsw.gov.au)

Monitoring Period	Jan-23						
Date Published	13 February 2023						
EPA Licence No.	13091						
EPA Licence Hyperlink	<a href="https://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=211659&amp;SYSUID=1&amp;LICID=13091">https://app.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=211659&amp;SYSUID=1&amp;LICID=13091</a>						
Licensee Name	KIMBRIKI ENVIRONMENTAL ENTERPRISES PTY LIMITED						
Licensee Address	PO BOX 196, Terrey Hills, NSW 2084						
Monitoring Location (EPA Point 1)	Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 1)						
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Mean value	Median value	Max. value
Explanatory Notes	No surface water discharge occurred from this monitoring point during the month.						
Monitoring Location (EPA Point 2)	Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 2)						
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Mean value	Median value	Max. value
Explanatory Notes	No surface water discharge occurred from this monitoring point during the month.						
Monitoring Location (EPA Point 3)	Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 3)						
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Mean value	Median value	Max. value
Explanatory Notes	No surface water discharge occurred from this monitoring point during the month.						
Monitoring Location (EPA Point 21)	Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 21)						
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Mean value	Median value	Max. value
Conductivity	µS/cm (Note 1)	Daily during any discharge	7	201	302	295	382
Explanatory Notes	(Note 1) µS/cm (microsiemens per centimetre)						
Monitoring Location (EPA Point 22)	Enclosed Ground Level Flare in the North-Eastern corner of the Premises. Please refer to the map, Kimbriki Monitoring Sites.pdf, for location (EPA 22)						
Pollutant	Units of measure	Monitoring frequency required by licence	No. of times measured during month	Min. value	Mean value	Median value	Max. value
Volumetric flowrate	m <sup>3</sup> /h (Note 1)	Continuous	Continuous	0 (Note 2)	419.8	424.0	454.0
Explanatory Notes	(Note 1) m <sup>3</sup> /h (cubic metres per hour) (Note 2) Zero value due to: 1. Flare was shut down on 17th Jan 2023 for ~0.25 hours due to flare shutdown, possibly due to stormy weather. No alarms. The flare was restarted remotely. 2. Flare was shut down on 18th Jan 2023 for ~3.25 hours due to a flame failure. The flare was restarted remotely. 3. Flare was shut down on 24th Jan 2023 for ~4.5 hours due to power supply outage. The flare was restarted remotely.						